 <p><b>Namibia Civil Aviation Authority</b> Air Navigation Service Aeronautical Information Management</p>	<h2>Daily NOTAM Bulletin</h2>	Effective Date: 15 Sep 2018
	AIM SSI -001 F -03	Version 2

### AERONAUTICAL INFORMATION SERVICES

Tel: +264-61-702087/83/80  
 Fax: +264-61-702088  
 Telex: 50-908) 811/2 WK  
 E-mail: [aisc@dca.com.na](mailto:aisc@dca.com.na)  
 Website: [www.dca.com.na](http://www.dca.com.na)

NAMIBIA CIVIL AVIATION AUTHORITY  
 Private Bag 12003  
 Ausspannplatz  
 Windhoek  
 NAMIBIA

### DAILY NOTAM BULLETIN

[http://www.dca.com.na/Notam/Notam\\_Bulletin.pdf](http://www.dca.com.na/Notam/Notam_Bulletin.pdf)

Enquiries: AISO

Our Ref: NTMS 2017

21<sup>st</sup> October 2018

FYGF	A0094/18	1803330747	PERM	NO FOREIGN REGISTERED CIVILIAN ACFT ALLOWED TO LAND AT FYGF AD WITHOUT GRANTED PERMISSION FM THE MINISTRY OF DEFENCE (MOD), OFFICE OF CHIEF OF DEFENCE (CDF) PRIOR ARRANGEMENT SHOULD BE MADE FOR AUTHORIZATION AT THE FOLLOWING ADDRESS: MOD, CDF PRIVATE BAG 13307 WINDHOEK FAX 061258215
FYGF	B0101/18	1810181513	1812311500	GFV DME IS SERVICABLE ON ONE CHANNEL
FYHO	C0068/18	1805030946	PERM	PILOTS AND OPERATORS ARE ADVISED THAT UNEXPECTED WIND SHEAR AND TURBULENCE HAVE BEEN REPORTED WHEN APPROACHING RWY 18/36, ON SHORT FINAL AND DURING FLARE. DUE TO SOFT (IRREGULAR) RWY SURFACE AT HOANIB, IT IS RECOMMENDED THAT NO ACFT NOT SUITABLY EQUIPPED FOR SOFT SURFACES BE OPERATED INTO THE AIRSTRIP. PILOTS TO MAKE INQUIRIES ABOUT OPERATING CONDITIONS AT: +264 61 274 200.
FYKA	C0049/18	1803330758	PERM	NO FOREIGN REGISTERED CIVILIAN ACFT ALLOWED TO LAND AT FYKA AD WITHOUT GRANTED PERMISSION FM THE MINISTRY OF DE FENCE (MOD), OFFICE OF CHIEF OF DEFENCE (CDF) PRIOR ARRANGEMENT SHOULD BE MADE FOR AUTHORIZATION AT THE FOLLOWING ADDRESS: MOD, CDF PRIVATE BAG 13307 WINDHOEK FAX 061258215
FYKH	C0159/18	1811010000	1811072359 EST	GLID ACT IN THE VCY OF FYKH WILL FLY WITH LATERAL LIMITS: 2308S01801E-2316S01808E THEN CLOCKWISE ON 60DME ARC WHV 2327S01714E-2317S01716E THEN CLOCKWISE ON 50DME WHV TO STARTING POINT, TFC INFOR PROVIDED WHEN AVBL ON FREQ 123.8MHZ. F)GND G)FL145)

1

Please Note:

It is the responsibility of the operator to routinely monitor the DCA Website for the latest NOTAM bulletin update.



**Namibia Civil Aviation Authority**  
**Air Navigation Service**  
**Aeronautical Information**  
**Management**

## Daily NOTAM Bulletin

Effective Date:  
15 Sep 2018

AIM SSI -001 F -03

Version 2

FYKM	A0331/18	1808182200	1810182200	THE FOLLOWING DECLARED DISTANCES IN METERS ARE AVBL FOR: RWY TORA ASDA TODA LDA 27 2292 2292 2292 2292 09 2292 2292 2292 2292  COORDINATES: THR27 ELEV 173757.12S0241113.96E 3125.93FT THR09 173809.55S240957.74E 3143.67FT
FYKM	B0075/18	1807270600	PERM	AERODROME CONTROL TOWER (TWR) HOURS OF OPS/SERVICE ARE AS FOLLOWS: MON-FRI: 0600-1030 AND 1100-1400 SAT: CLSD SUN: 0700-1300
FYKM	B0094/18	1810062200	1901032200	ANNUAL WGS-84 SURVEY NOT CMPL. ALL AD DATA NOT VALIDATED.
FYKT	B0096/18	1810062200	1901032200	ANNUAL WGS-84 SURVEY NOT CMPL. ALL AD DATA NOT VALIDATED.
FYLZ	B0013/18	1802051512	1812311400	ATIS SERVICES ON FREQ.126.6MHZ OUT OF SERVICE DUE TO FAULTY EQUIPMENT.
FYLZ	B0091/18	1810010600	1812311400	AERODROME CONTROL TOWER (TWR) HOURS OF OPS/SERVICE MON-FRI 06000-0930 AND 1000-1400 SAT- NIL ATC SUN 0700-1300
FYLZ	B0093/18	1810062200	1901032200	ANNUAL WGS-84 SURVEY NOT CMPL. ALL AD DATA NOT VALIDATED.
FYRN	C0098/18	1806250912	PERM	NEW RHINO CAMP DIMENSIONS ARE AS FOLLOWS : COORDINATES 200211S0135035E RWY DESIGNATORS RWY09/27 DISPLACED TO A POINT OF 100M FM THE INITIAL POINT, THE FOLLOWING DECLARED DISTANCES IN METERS ARE AVBL FOR RWY09 TODA: 1400M LDA: 1300 M ,DISTANCE IN METERS FOR RWY27 TODA: 1400 LDA: 1300 FOR FURTHER INFO CONTACT 061 – 255735.
FYRU	B0095/18	1810062200	1901032200	ANNUAL WGS-84 SURVEY NOT CMPL. ALL AD DATA NOT VALIDATED.
FYOA	A0176/18	1805161355	PERM	AIRAC AIP SUP01/2018 CNL.
FYOA	A0373/18	1809201444	PERM	ONDANGWA TMA A AND TMA B AS DEPICTED IN AIP ENR2.1-8 COMPLETELY WITHDRAWN
FYOA	A0379/18	1809251437	1812292359	RWY08/26 LENGTH 2824M THR RWY08 DISPLACED BY 162M RWY08/26 WIDTH 45M RWY08/26 PCN 48/F/B/X/T TWY PCN 12/F/D/Y/U

2

Please Note:

It is the responsibility of the operator to routinely monitor the DCA Website for the latest NOTAM bulletin update.



**Namibia Civil Aviation Authority**  
**Air Navigation Service**  
**Aeronautical Information**  
**Management**

## Daily NOTAM Bulletin

Effective Date:  
15 Sep 2018

AIM SSI -001 F -03

Version 2

				APRON PCN 12/F/D/Y/U
FYOA	B0044/18	1804260800	PERM	THR RWY 08 DISPLACED BY 163M TOTAL RWY LENGTH IS 2824M. DECLARED DISTANCE NOT DETERMINED.
FYOA	B0045/18	1804260751	PERM	RNP RWY 08 DUE DTHR BARO VNAV NOT AUTHORISED X LNAV MDA (OCH) INCREASED TO 4100(501)FT
FYOA	B0074/18	1807231700	1810232359	UNSERVICEABLE AREAS ON THE APRON MARKED WITH BARRICADES.
FYOA	B0079/18	1808010739	1811022300	AERODROME HOURS OF OPS/SERVICE SUNDAY TO FRIDAY:0400 TO 1800 SATURDAY: 0400 TO 1400 AIRPORT AFTERS HOURS OPERATION REQUEST MR EN SHOOMBE CELL:+264811441633  shoombee@airports.com.na
FYOA	B0092/18	1810050945	1901012200 EST	ANNUAL WGS-84 SURVEY NOT COMPLETED. ALL AERODROME DATA NOT VALIDATED.
FYOA	B009918	181018	PERM	NIL ATC VOICE RECORDING FAC AND RETENTION AVBL AT FYOA TWR.
FYOA	B0100/18	1810181512	1812311500	OAV DME IS SERVICABLE ON ONE CHANNEL
FYOA	B0102/18	1810191627	1810281730	ONDANGWA ATC HOURS OF DUTY WILL BE AS FOLLOWS: MON,WED AND FRI: 0500-1000 AND 1200-1730 TUE AND THU :0500- 1000 AND 1130 - 1730 SAT: NIL SUN: 0500-1000 AND 1300-1730 UTC
FYOG	B0084/18	1808090345	PERM	HAND AMEND NAMIBIAN AIP FYOG AD2-11 DATED 10 NOV 2016 COMMUNICATION FAILURE PROCEDURE, REPLACE OG201 WITH OG202.
FYWB	A0412/18	1810191809	1811081800	E)THE FOLLOWING DECLARED DISTANCES IN METERS ARE AVBL FOR: RWY TORA ASDA TODA LDA 27 3440 3440 3440 3440 09 3440 3440 3440 3440 RWY WIDTH 60M: COORDINATES: THR27 225828.55S0143947.07E THR09 225903.14S0143752.23E

3

Please Note:

It is the responsibility of the operator to routinely monitor the DCA Website for the latest NOTAM bulletin update.



**Namibia Civil Aviation Authority**  
**Air Navigation Service**  
**Aeronautical Information**  
**Management**

## Daily NOTAM Bulletin

Effective Date:  
15 Sep 2018

AIM SSI -001 F -03

Version 2

				ELEVATION 235.11FT
FYWB	A0313/18	1808151501	1811151500	SIMUL MOV OF ACFT ON RWY09/27 AND THE PARL TWY IS NOT ALLOWED,DUE TO INSUFFICIENT SEPARATION DIST BTN THE RWY CL AND THE TWY CL.
FYWB	A403/18	1810081300	1901081300	ANNUAL WGS-84 SURVEY NOT CMPL. ALL AD DATA NOT VALIDATED.
FYWB	A405/18	1810120900	1810311300	NIL AVGAS AVBL
FYWB	A0406/18	1810151839	1811081800	FYWB AP HRS OF OPS ARE AS FOLLOWS: 06H00-15H00 EXCEPT IN THE CASE OF EMERG OR WITH PRIOR PERMISSION ON  CONTACT NO: +264 64 271123, NO ACFT MAY LAND OR TKOF OUTSIDE AD OPR HRS. IMMIGRATIONS AND CUSTOMS AVBL ON REQ.
FYWB	A0411/18	1810200000	1901052359	STS AD LICENSE ISSUED.
FYWB	A0413/18	1810200601	1812311600	FYWB TWR HOURS OF OPS/SERVICE. MON-FRI 0600-1600, SAT 0700 - SUN 1500 TIME MAY CHG ON SHORT NOTICE.
FYWE	A0342/18	1808281428	1811281500 EST	NIL CERTIFIED MET SENSORS AVAILABLE, ATS PROVIDING MET FROM UNCALIBRATED SYSTEM WHICH MAY NOT MEET ANNEX 3 REQUIREMENTS.
FYWE	A0343/18	1808281500	1811281500 EST	EROS AD MET OFFICE DOES NOT SEND A METAR AN HOUR PRIOR TO THE OPS OF THE AD.
FYWE	A0397/18	1810062200	1901032200	ANNUAL WGS-84 SURVEY NOT CMPL. ALL AD DATA NOT VALIDATED.
FYWE	A0390/18	1809282200	1812282200	ABN OUT OF SERVICE
FYWE	A0409/18	1810180600	1810261500	CRACK SEALING ON RWY01/19 AND TWY ALPHA, GRASS CUTTING ON EDGE OF RWY01/19 AND 09/27.
FYWH	A0136/18	1804241623	PERM	HAND AMEND NAMIBIAN AIP, FYWH AD 2.11 METEOROLOGICAL INFORMATION PROVIDED. 2. MET HRS OF OPS/SERVICE ARE AS FOLLOWS: FORECAST H24 ASSISTANT MET TECHNICIAN 04H00-18H00 CONTACT DETAILS +264 62 540059 AND +264 62

4

Please Note:

It is the responsibility of the operator to routinely monitor the DCA Website for the latest NOTAM bulletin update.



**Namibia Civil Aviation Authority**  
**Air Navigation Service**  
**Aeronautical Information**  
**Management**

## Daily NOTAM Bulletin

Effective Date:  
15 Sep 2018

AIM SSI -001 F -03

Version 2

				540327.
FYWH	A0249/18	1807121030	PERM	DUE MISALIGNMENT WITH NAMCAR 91.06.33 HAND AMEND NAMIBIA AIP ENR 1.1 GENERAL RULES 1.1.B) DELETE FOLLOWING TEXT "UNLESS THE FLIGHT CAN BE MADE WITHOUT HAZARD OR NUISANCE TO PERSONS OR PROPERTY ON THE GROUND OR WATER".
FYWH	A0281/18	1807241240	PERM	AIC SERIES A04/18 CNL
FYWH	A0341/18	1808281425	1811281500 EST	ALL CERTIFIED MET SENSORS FAILED, ATS PROVIDING MET FROM UNCALIBRATED SYSTEM WHICH MAY NOT MEET ANNEX 3 REQUIREMENTS.
FYWH	A0346/18	1808312359	1811300400	D) DAILY 2359-0400 THE APRON MARKINGS AT FYWH ARE NOT COMMENSURATED TO TRAFFIC THAT FYWH INTENDS TO SERVE, THEREFORE APRON MARKINGS MUST BE DISREGARDED AND THE PILOTS MUST FOLLOW THE MARSHALERS SIGNALS.
FYWH FIR	A0345/18	1808302000	1811282359	FYWH STS OF AD CERTIFICATION ISSUED 30 AUG 2018 WITH CONDITIONS-VALIDITY PERIOD UNTIL 28 NOV 2018. CERTIFICATION ISSUED PENDING RESOLUTION OF SAFETY AND SECURITY OPR FINDINGS TO INCLUDE AT MINIMUM: 1. MIXING OF INTL AND DOM PAX 2. MIXING OF SECURITY SCREENED AND UNSCREENED PERSONS 3. NON-SIMULTANEOUS MOVEMENT OF ACFT BTN TWY AND TWY 4. POSITIONING OF GA AND COMM APN INCL PRKG, LOADING AND UNLOADING AREAS 5. SECURITY SCREENING CHECKPOINT CONGESTION.
FYWH	A0324/18	1808170430	1811201700	DAILY 0430-1700 APPROACH CONTROL TRAINING TAKING PLACE IN FYWH TMA ON FREQ120.5MHZ.
FYWH FIR	A0344/18	1808301207	PERM	AIP SUP S03/18 CNL.
FYWH FIR	A0375/18	1809201815	PERM	HAND AMEND AIP FYOA AD 2-9 FYOA AD 2.17 ATS AIRSPACE POINT 6 REMAKS DELETE WORDS COMBINED WITH APP. FYOA AD 2.18 ATS COMMUNICATION FACILITIES DELETE IN TOTO FOURTH LINE BEGINNING WITH

5

Please Note:

It is the responsibility of the operator to routinely monitor the DCA Website for the latest NOTAM bulletin update.



**Namibia Civil Aviation Authority**  
**Air Navigation Service**  
**Aeronautical Information**  
**Management**

## Daily NOTAM Bulletin

Effective Date:  
15 Sep 2018

AIM SSI -001 F -03


Version 2

				APPROACH.
FYWH FIR	A0350/18	1809031227	1811072359	HAND AMEND AIP ENR4.4-3 NAME-CODE DESIGNATOR UNLIL COORDINATES TO READ S211111.49E0170138.38
FYWH FIR	A0363/18	1809151000	PERM	HAND AMEND NAMIBIAN AIP ENR 4.4 NAME CODE DESIGNATOR ATUPI COORDINATOR TO READ 231013.74S0170755.40E
FYWH FIR	A0368/18	1809171400	PERM	HAND AMEND NAMIBIA AIP SUP S08/18 PARAGRAPH 5 (A) TRANSPONDER MANDATORY ZONE FIRST SENTENCE TO READ X TRANSPONDER MANDATORY ZONES ARE ESTABLISHED DURING THE GLIDING SEASON TO ENSURE GREATER AWARENESS OF GLIDER TRAFFIC IN AREAS THAT MAY HAVE HIGH DENSITY IFR TRAFFIC OPERATIONS.
FYWH FIR	A0395/18	1811010000	1811072359 EST	REF NA AIP ENR 1.6 TMZ ABV FL145 WI CLASS E GLID AIRSPACE FYBJ/FYPO/FYKH/FYVF AND KALAHARI NATIONAL PARK. TMZ FL145 AND ABV ONLY APPLICABLE IN FLW AREAS WHEN WI GLID AREA 1.WHV RAD 155 TO 205 WI 80DME 2.WBV WI 80DME 3.45NM ARC FM FYLZ ARP 4.15NM EITHER SIDE ATS RTE R987 5.15NM EITHER SIDE ATS RTE G653 F)FL145 G)FL195)
FYWH FIR	C0162/18	1810091522	PERM	HAND AMEND NAMIBIAN AIP FYSM AD 2.23 PARA 1.4 A PERM DROP ZONE HAS BEEN DECLARED AT CHINA TOWN 223350S0143434E 6NM NORTH OF SWAKOPMUND. DLY SKYDIVING ACTIVITIES TAKING PLACE DLY BTN SR AND SS. PARACHUTE ACFT WILL OPERATE ON 126.3MHZ AND 122.5MHZ  F) GND G) FL115
FYWH FIR	A404/18	1810110001	1810252359	TRIGGER NTM: PERM AIRAC AIP SUP S06/18. GLOBAL NAVIGATION SATELLITE SYSTEM.
FYWH FIR	A0410/18	1810250500	1810251200	FYR133 ACTIVE, LIVE FIRING EXERCISE.  F) GND G) FL145
FYWH FIR	C0171/18	1810261330	1810261430	BLASTING WILL TAKE PLACE AT BEIFANG MINING SERVICES ON THE C34 ROAD DEFINED BY THE

6

Please Note:

It is the responsibility of the operator to routinely monitor the DCA Website for the latest NOTAM bulletin update.

 <p><b>NCAA</b> NAMIBIA CIVIL AVIATION AUTHORITY</p> <p><b>Namibia Civil Aviation Authority</b> <b>Air Navigation Service</b> <b>Aeronautical Information</b> <b>Management</b></p>	<p><b>Daily NOTAM Bulletin</b></p>	<p>Effective Date: 15 Sep 2018</p>
	<p>AIM SSI -001 F -03</p>	<p>Version 2</p>

				<p>FOLLOWING COORDINATE: 224026S0143442E</p> <p>F) GND G) 1000FT AGL</p>
--	--	--	--	--

7

Please Note:

It is the responsibility of the operator to routinely monitor the DCA Website for the latest NOTAM bulletin update.