



REPUBLIC OF NAMIBIA

**MINISTRY OF WORKS AND TRANSPORT**

AERONAUTICAL INFORMATION SERVICES

Tel: +264-61-702087/83/80  
Fax: +264-61-702088  
Telex: 50-908) 811/2 WK

DIRECTORATE OF CIVIL AVIATION  
Private Bag 12003  
Ausspannplatz  
Windhoek  
NAMIBIA

E-mail: [ais@dca.com.na](mailto:ais@dca.com.na)  
Website: [www.dca.com.na](http://www.dca.com.na)

**DAILY NOTAM BULLETIN**

[http://www.dca.com.na/Notam/Notam\\_Bulletin.pdf](http://www.dca.com.na/Notam/Notam_Bulletin.pdf)

Enquiries: AISO

Our Ref: NTMS 2017

23<sup>rd</sup> March 2018

<b>FYBJ</b>	A0342/17	1711030000	PERM	TIBA FREQ ASSIGNED AT FYBJ 123.600MHZ, CS BITTERWASSER TFC. F)GND G)3000AGL
<b>FYDC</b>	C0069/15	1506041227	PERM	TODA 1400 METERS DISPLACED THRESHOLD RWY05 100 METERS DISPLACED THRESHOLD RWY23 260 METERS ALL TURNS TO BACKTRACK MUST BE ON HARD STAND. TEARDROPS AT RWYS EXTREMITIES ONLY.
<b>FYDN</b>	C0107/15	1509091130	PERM	THRESHOLD RWY07 AND RWY25 DISPLACED TO A POINT OF 150M FROM THE INITIAL POINT,THE FOLLOWING DECLARED DISTANCES IN METERS ARE AVAILABLE FOR RWY07 TODA: 1550 LDA : 1400 DISTANCE IN METERS FOR RWY25 TODA: 1550 LDA : 1400
<b>FYGF</b>	C0049/18	1803330747	PERM	NO FOREIGN REGISTERED CIVILIAN ACFT ALLOWED TO LAND AT FYGF AD WITHOUT GRANTED PERMISSION FM THE MINISTRY OF DE FENCE (MOD), OFFICE OF CHIEF OF DEFENCE (CDF) PRIOR ARRANGEMENT SHOULD BE MADE FOR AUTHORIZATION AT THE FOLLOWING ADDRESS: MOD, CDF PRIVATE BAG 13307 WINDHOEK FAX 061258215
<b>FYHO</b>	C0020/18	1802070821	PERM	PILOTS AND OPERATORS ARE ADVISED THAT UNEXPECTED WIND SHEAR AND TURBULENCE HAVE BEEN REPORTED WHEN APPROACHING RWY 18/36, ON SHORT FINAL AND DURING FLARE. DUE TO AFOREMENTIONED AND THE SOFT RWY SURFACE AT HOANIB, IT IS RECOMMENDED THAT NO ACFT SMALLER THAN C208, OR ACFT THAT ARE NOT SUITABLY EQUIPPED FOR SOFT SURFACES BE OPERATED

Please Note:

It is the responsibility of the operator to routinely monitor the DCA Website for the latest NOTAM bulletin update.

				INTO THE AIRSTRIP.
<b>FYKM</b>	B0027/18	1803200600	1803311500	WIP, CLEANING THE RWY AT FYKM AP.
<b>FYKT</b>	A0396/17	1711300500	PERM	REF AIP FYKT AD 2.15 CHART WITHDRAWN DUE TO NON MAINTENACE OF THE PROCEDURE
<b>FYKH</b>	A0341/17	1711030000	PERM	TIBA FREQ ASSIGNED AT FYKH 120.250MHZ, CS KIRIPOTIB TFC. F)GND G)3000AGL
<b>FYLZ</b>	B0089/17	1708081235	PERM	ERECTION OF WIND TURBINES FOR LUDERITZ TOWN COUNCIL FOR A WIND GENERATION PLANT, DEFINED BY THE FOLLOWING COORDINATES : 263820.67S0151058.97E 263812.77S0151114.21E 263759.38S0151140.00E F) GND G) 200M AMSL
<b>FYLZ</b>	B0096/17	1708220001	PERM	HAND AMEND NAMIBIAN AIP GEN 3.3-6 ATS UNIT ADDRESS LIST, ADD UNIT NAME LUDERITZ TWR. POSTAL ADDRESS: NIL. TEL NO. +26463703590/1 OR 26463202228, TELEFAX NO. +26463703599. AFS ADDRESS FYLZZTZX.
<b>FYLZ</b>	B0097/17	1708220001	PERM	HAND AMEND NAMIBIAN AIP ENR 1.10-3.1 FILING OF FLIGHT PLANS TELEPHONICALLY, ADD STATION LUDERITZ TEL. +26463703590/1 OR +26463202228.
<b>FYLZ</b>	B0098/17	1708220001	PERM	HAND AMEND NAMIBIAN AIP GEN 3.1-5 PRE-FLIGHT INFORMATION SERVICE AT AIRPORTS, ADD LUDERITZ AERODROME (FYLZ): NOTAM & AIP.
<b>FYLZ</b>	B0099/17	1708220001	PERM	HAND AMEND NAMIBIAN AIP ENR 1.7 ALTIMETER SETTING PROCEDURE, ADD LUDERITZ TRANSITION ALTITUDE 10 000FT.
<b>FYLZ</b>	B007/18	1801191000	1803311400	ATC H.O.D ARE: MON – FRI : 0600 – 0930 AND 1000 - 1400 SAT : NIL SUN : 0700 – 1300. ALL TIMES IN UTC.
<b>FYLZ</b>	B0013/18	1802051512	1812311400	ATIS SERVICES ON FREQ.126.6MHZ OUT OF SERVICE DUE TO FAULTY EQUIPMENT.
<b>FYKA</b>	C0049/18	1803330758	PERM	NO FOREIGN REGISTERED CIVILIAN ACFT ALLOWED TO LAND AT FYKA AD WITHOUT GRANTED PERMISSION FM THE MINISTRY OF DE FENCE (MOD), OFFICE OF CHIEF OF DE FENCE (CDF) PRIOR ARRANGEMENT SHOULD BE MADE FOR AUTHORIZATION AT THE FOLLOWING ADDRESS: MOD, CDF PRIVATE BAG 13307 WINDHOEK FAX 061258215
<b>FYRN</b>	C0035/18	1707210600	PERM	NEW RHINO CAMP DIMENSIONS ARE AS FOLLOWS : COORDINATES 195837S0131502E RWY DESIGNATORS RWY09/27 DISPLACED TO A POINT OF 100M FM THE INITIAL POINT, THE FOLLOWING DECLARED DISTANCES IN METERS ARE AVBL FOR RWY07 TODA: 1400M LDA: 1300 M ,DISTANCE IN METERS FOR RWY25 TODA: 1400 LDA: 1300 FOR FURTHER INFO CONTACT 061 – 255735.
<b>FYTM</b>	C0014/18	1803151620	PERM	AD CLSD, NO ACFT WILL BE ALLOWED TO LAND, NOT EVEN EMERGENCY FLIGHT. THE RWY OBSTRUCTED TO PREVENT UNLAWFUL

Please Note:

It is the responsibility of the operator to routinely monitor the DCA Website for the latest NOTAM bulletin update.

				USE BY OPERATORS. NOTE NOTAM C120/17 ISSUED WITH INCORRECT EXPIRY DATE HEREBY CORRECTED.
<b>FYTM</b>	C0048/18	1803201057	PERM	FYTM-TSUMEB IS AN UNLICENSED AND UNREGISTERED AD. THE OWNER AND/OR OPERATOR OF THE AD IS SUBJECT TO A DECISION STILL PENDING FROM THE HIGH COURT OF NAMIBIA AND THEREFORE THE AD ADMINISTRATIVE AND OPERATIONAL DETAILS LISTED IN THE NAMIBIA AIP AND WITH THE NCAA ARE NOT VALID. THE NAMIBIA CIVIL AVIATION AUTHORITY THEREFORE WITHDRAWS ALL AERONAUTICAL INFO AND PRIVILEGES GRANTED REGARDING THIS AERODROME.
<b>FYOA</b>	B0010/18	1802010500	1804301800	ONDANGWA AIRPORT OPERATION HOURS : SUN-FRI : 0500-1800 SAT : 0500-1400 ALL TIMES UTC
<b>FYOA</b>	B0028/18	1803210513	1806192200	INTERSECTION B CLOSED.
<b>FYOA</b>	B0022/18	1803130410	1806122000	UNSERVICEABLE AREA ON THE APRON MARKED WITH BARRICADES , PILOTS TO EXERCISE CAUTION.
<b>FYPO</b>	A0340/17	1711030000	PERM	TIBA FREQ ASSIGNED AT FYPO 120.200MHZ, CS POKWENI TFC. F)GND G)3000AGL
<b>FYSM</b>	C0008/18	1801250813	PERM	ACFT NOT PERMITTED TO USE TWY FM HANGAR AREA TO APN/THR RWY17 FOR TAKE-OFF OR LDG. ALL ACFT INCL MICROLIGHT TO USE DESIGNATED RWYS FOR TAKE-OFF AND LDG ONLY.
<b>FYWB</b>	A0057/18	1802151500	1805151501	SIMULTANEOUS MOVEMENT OF AIRCRAFT ON RWY09/27 AND THE PARALLEL TWY IS NOT ALLOWED,DUE TO INSUFFICIENT SEPARATION DISTANCE BETWEEN THE RWY CENTRELINE AND THE TWY CENTRELINE.
<b>FYWB</b>	A0082/18	1803140600	1804151800	ATC HOURS OF DUTY ARE AS FOLLOWS: MON – FRI : 0600 – 1600 UTC SAT & SUN : 0700 – 1500 UTC
<b>FYWB</b>	A0086/18	1803151801	1804151800	FYWB AIRPORT HOURS OF OPERATION WILL BE AS FOLLOWS : 06H00 TO 15H00 UTC, EXCEPT IN THE CASE OF EMERGENCY OR WITH PRIOR PERMISSION ON CONTACT +264 64 271123, NO AIRCRAFT MAY TAKE-OFF OR LAND OUTSIDE AD OPERATING HOURS, IMMIGRATION AND CUSTOMS AVBL ON REQUEST.
<b>FYWB</b>	A0397/17	1711300500	PERM	REF AIP FYWB AD 2. 13 CHART WITHDRAWN DUE TO NOT SHOWING TRUE REPRESENTATION OF THE AIRPORT.
<b>FYWB</b>	A0090/18	1803191801	1804191800	THE FOLLOWING DECLARED DISTANCES IN METERS ARE AVBL FOR : RWY TORA ASDA TODA LDA 27 3440 3440 3440 3440 09 3440 3440 3440 3440 RWY WIDTH 60M:

Please Note:

It is the responsibility of the operator to routinely monitor the DCA Website for the latest NOTAM bulletin update.

				COORDINATES : THR27 225828.55S0143947.07E THR09 225903. 14S0143752.23E ELEVATION 235. 11FT
<b>FYWB</b>	A0025/18	1802051511	1805311400	ATIS SERVICES ON FREQ.127. 0MHZ OUT OF SERVICE DUE TO FAULTY EQUIPMENT.
<b>FYWB</b>	A0075/18	1803071438	1805312359	ILS WBI NOT TO BE USED. REQ GND INFRASTRUCTURE AND PROTECTION NOT IN PLACE.
<b>FYWE</b>	A0262/17	1709030330	1804011900	EROS AIRPORT HOURS OF DUTY ARE AS FOLLOWS: MON – FRI : 0330 – 1900 UTC SAT : 0330 – 1800 UTC SUN : 0330 – 1900 UTC
<b>FYWE</b>	A382/17	1711250400	PERM	HAND AMEND AIP FYWE AD. 2.11 HOURS OF SERVICE. MON – FRI : 0400 – 1800 SAT - SUN : 0400 -1230, 1430 – 1530 , 1730 – 1800.
<b>FYWE</b>	A0326/17	1710240600	PERM	DUE TO NON-SIMULTANEOUS OPERATIONS ON THE MANOEUVRING AREA AT FYWH , ALL TRAFFIC INTENDING TO DEPART FROM FYWE TO FYWH ARE REQUIRED TO REQUEST FOR AND RECEIVE A START UP CLEARANCE FROM FYWE TOWER.
<b>FYWE</b>	A0089/18	1803190723	1804122200	PAPI RWY01 OUT OF SERVICE.
<b>FYWE</b>	A0097/18	1803230600	1803231500	WIP NO TOUCH AND GO ALLOWED.
<b>FYWH</b>	A0334/17	1711011200	PERM	1. AD RESTRICTION TO CODE E AIRCRAFT WITH OUTER MAIN GEAR SPAN OF 13 METRES OR LESS.  2. SIMULTANEOUS MOVEMENT OF AIRCRAFT ON RWY08/26 AND THE PARALLEL TWY IS NOT ALLOWED, DUE TO INSUFFICIENT SEPARATION DISTANCE BETWEEN THE RWY CENTRELINE AND THE TWY CENTRELINE.
<b>FYWH</b>	A0069/18	1803060600	1803290200	WIP ON MOVEMENT AREA .
<b>FYWH</b>	A0021/18	1801260700	1804300000	THE APRON MARKINGS AT FYWH ARE NOT COMMENSURATED TO TRAFFIC THAT FYWH INTENDS TO SERVE, THEREFORE THE APRON MARKINGS MUST BE DISREGARDED AND THE PILOTS MUST FOLLOW THE MARSHALLERS SIGNALS.
<b>FYWH</b>	A0339/17	1711030000	PERM	TIBA FRQ ASSIGNED AT FYVF 123.200MHZ, CS VERONICA TFC
<b>FYWH</b>	A0022/18	1801280500	1803281700	AD TRAINING TAKING PLACE AT FYWH TWR. PILOTS TO EXERCISE CAUTION AND PATIENCE.
<b>FYWH</b>	A0381/17	1711250400	PERM	HAND AMEND AIP FYWH AD 2.11 HOURS OF SERVICE 04H00-18H00
<b>FYWH</b>	A0395/17	1801092359	PERM	FLIGHT PLANS FILED VIA THE INTERNET BRIEFING WILL ONLY BE VALIDATED FM 0330 UNTIL 1900 UTC, OUT OF THESE HRS MEDEVAC FLIGHT PLANS CAN BE FILLED WITH FYWH

				ACC.
<b>FYWH</b>	A0336/17	1711020230	1803242030	AERODROME OPERATION HOURS: MON – SAT : 0230 – 2030 UTC SUN : 0300 – 2030 UTC
<b>FYWH</b>	A0400/16	1611011400	PERM	FYWH ILS/DME CH40X 110.3 MHZ IS WITHDRAWN FROM SERVICE. AWAITING REPLACEMENT OF EQUIPMENT.
<b>FYWH FIR</b>	A0091/18	1803270600	1803291230	FYR133 OSERIKARI WEAPONS RANGE ACTIVATED. F). GND G). FL145
<b>FYWH FIR</b>	A0093/18	1803201038	PERM	HAND AMEND NAMIBIA AIP – WITHDRAW FOLLOWING PAGES FROM AIP FYTM AD 2-1 TO FYTM AD 2-8.
<b>FYWH FIR</b>	A0135/17	1704140001	PERM	AIC 17.2 ON GLIDING AND PARACHUTING CANCELLED. REF AIC 17.2 NAMIBIAN AIC.
<b>FYWH FIR</b>	A0007/18	1801120001	PERM	HAND AMD NAMIBIA AIP ENR 3.1-1-3.1-3 X DELETE (RNP TYPE) IN HEADING TITTLE COLUMN 1.
<b>FYWH FIR</b>	A0078/18	1803091751	1804062359	FYWH MET PROVIDING OBSERVATION ONLY X TAF PREPARATION TEMPORALILY ISSUED BY FYWW MWO CONTACT: +26461 2877028
<b>FYWH FIR</b>	A0098/18	1803221830	1803222030	TOPSKY SURVEILLANCE OUT SERVICE.

Please Note:

It is the responsibility of the operator to routinely monitor the DCA Website for the latest NOTAM bulletin update.